



Unwind chart

For machine applications, please verify the unwind of the roll.


Wound out




Head first



Bottom first




Right side first




Left side first


Wound in




Head first



Bottom first



Right side first



Left side first